



OFFICE OF THE EXECUTIVE ENGINEER
कार्यपालक अभियंता कार्यालय
WORKSHOP DIVISION, कार्यशाला मण्डल,
ANDAMAN PUBLIC WORKS DEPARTMENT
अ०लो०नि०वि०,
PORT BLAIR, पोर्ट ब्लेयर



-15

No. DB-79/Edn/WSD/2024-25/ 539

Port Blair, dated the 07 Aug. 2024

To,

The Vice Principal
Govt. Secondary School,
Delanipur, Port Blair.

Subject :- Issue of Safety Certificate-reg

Ref :- 1-8/Building/VP/GSS/DP/2023-24/3308 dt.14/08/2023.

Sir,

With reference to your letter No. cited above it is to inform that the IEI work of the School building has been inspected by our Engineer and found that the internal electrical installation is in satisfactory condition. This is for your information.

Yours faithfully,

कार्यपालक अभियंता
Executive Engineer,
कार्यशाला मण्डल, अ०लो०नि०वि०, पोर्ट ब्लेयर
Workshop Division, APWD, Port Blair.

Copy to:-

1. The Assistant Engineer, Sub-Division-II under Workshop Division APWD,
Port Blair for information

कार्यपालक अभियंता
Executive Engineer,
कार्यशाला मण्डल, Workshop Division

Forwarded to Shri Shiva S.
G. II (maths)
CBSE I/c
P
V.P.

INSPECTION REPORT OF GOVT. SEC. SCHOOL, DELANIPUR, DATE 18.10.2023



a)	House No. and Type : Govt. Sec. School, Delanipur	Loacation : Delanipur P.O : Haddo Office Port Blair.
b)	Date of Inspection Physcially	18.10.2023
c)	Structured constructed and completion on	Structured constructed 2007 & Completion on 2009
S.No.	Item No	Remarks
A	Structure status	RCC frame structure is in good condition.
1	WALLS	
1.1	Cracks	Crack are not found
1.2	Wall condition	Sound and good condition
2	Floors	
2.1	CC Floor	Old block CC floor to be repair
2.2	Cracks	Old block Ground floor.
2.3	Settlements	Not found
3	Doors, windows, ventilators & cupboards	
3.1	Glass panes broken	Partially broken
3.2	Panels in shutters broken	Partially broken
1.1.1	Tower bolts	Function good
4	Roofs	
4.1	Leakages / Damps Patches	Not appear or found
5	Water supply and sanitary fiitings	
5.1	Leakage in pipe joints	Not found
5.2	Functioning of washers	Good
5.3	Functioning of traps in fittings	Good
5.4	Functioning of floor traps	Good
5.5	Functioning of overhead / low level cistern	Good
5.6	Condition of overhead tank	Good
5.7	Cleaning of overhead tank	Frequently cleaning every months

6	External Services	
6.1	Manhole Covers	Well function
6.2	Plinth protection	Good
6.3	Cleaning of storm water drain	Well function
6.4	Approach access	Found good
7	Finishing	
7.1	White washing / colour washing / Distemper	Faded need repainting
(a)	When it was done last	Last during 2014
(b)	When is it due	This year 2023
(c)	Existing condition	Faded.
7.2	Common Areas	
7.2.1	Railing staircase	Good condition
7.2.2	Staircase steps	Good condition
7.2.3	Staircase nosing	Good condition
7.2.4	Shafts	Good condition
8	Condition of R.C.C Structure	RCC frame structure of 02 Nos new double storied building is sound and in well condition. But in old double storied block RHS 04 Nos columns needed structural repair upto ground floor slab beam level. Hence this school building structure is safe.

Inspected on today the 18th October 2023 by :-

B.P.D.A.S.
Junior Engineer
Delanipur Section
Sub-Division No 1
B.N.D., A.P.W.D
Port Blair

Vice Principal
GSS Delanipur

Vice Principal
उप प्रधानाचार्य
Govt. Sec. School, Delanipur
राजकीय उच्च माध्यमिक विद्यालय विलापीपुर
Port Blair
पोर्ट ब्लेयर

Assistant Engineer-I
महाराजक अभियंता I
Port Blair North Division
Assistant Engineer
पोर्ट ब्लेयर (उत्तर) मण्डल
Port Blair North Division
अ लो नि बि पोर्ट ब्लेयर
A P W D Port Blair