

No. IFB (C/N)/2020/349

निरीक्षक अग्निदामन का कार्यालय

OFFICE OF THE INSPECTOR FIRE BRIGADE

अग्निदामन केन्द्र कार निकोबार

FIRE STATION CAR NICOBAR

Car Nicobar, dated the 06th March, 2021.



To
✓ The Principal
Govt. Sr. Sec. School
Campbell Bay.

Sub: - Fire Safety audit report - reg.
Ref: - IFB/CN/2017-18/158 dated 16/08/2018.

Sir,

This is to inform you that fire safety audit report has been forwarded to the Education officer, Nicobar district, C/Nicobar vide this office letter No. IFB/CN/2017-18/158 dated 16/08/2018 for strict compliance for fulfilling the fire safety recommendation immediately in respect of Govt. Schools at Campbell Bay. On re-inspection on 23/02/2021 it has been noticed that the fire fighting arrangements recommended in the Fire Audit Report has not yet been complied so far. Again a fresh audit has been conducted and detail report is furnished below:

GOVT. SR. SEC. SCHOOL, CAMPBELL BAY: Type of Building : Single storied semi RCC building with 05 Blocks:

Sl.No	Name of Extinguishers	Existing	Status	Recommendation
1.	Water CO ₂ Extinguisher (09 Ltrs)	03	U/S (old model)	03 Nos.
2.	Mech. Foam Ext.(09 Ltrs)	02	U/S (old model)	02 Nos.
3.	DCP Extinguisher (6kg)	02	U/S	02 Nos.
4.	CO ₂ Extinguisher (4.5kg)	01	OK	02 Nos. required
4.	Fire Bucket filled with sand and water.	02	OK	02 Nos. required

GOVT. PRIMARY SCHOOL, KAMAL BASTI: Type of Building : Single storied semi RCC building

Sl.No	Name of Extinguishers	Existing	Status	Recommendation
1.	Water CO ₂ Extinguisher (09 Ltrs)	01	U/S (old model)	01 No. required
2.	DCP Extinguisher (6kg)	01	U/S (old model)	01 No. required
3.	CO ₂ Extinguisher (4.5kg)	01	U/S	01 No. required
4.	Fire Bucket filled with sand and water.	Nil	--	03 Nos. required

GOVT. PRIMARY SCHOOL, RAJIV NAGAR: Type of Building : Single storied semi RCC building

Sl.No	Name of Extinguishers	Existing	Status	Recommendation
1.	Water CO ₂ Extinguisher (09 Ltrs)	--	--	01 No. required
2.	DCP Extinguisher (6kg)	01	U/S (old model)	01 No. required
3.	CO ₂ Extinguisher (4.5kg)	--	--	01 No. required
4.	Fire Bucket filled with sand and water.	Nil	--	03 Nos. required

GOVT. PRIMARY SCHOOL, MAKACHUA: Type of Building : Single storied semi RCC building

Sl.No	Name of Extinguishers	Existing	Status	Recommendation
1.	DCP Extinguisher (6kg)	--	--	02 nos.
2.	CO ₂ Extinguisher (4.5kg)	--	--	02 nos.
3.	Fire Bucket	--	--	03 nos. to filled with dry sand.

Contd.... P2/-

GOVT. SEC SCHOOL, GANDHI NAGAR: Type of Building : Single storied semi RCC building

Sl.No	Name of Extinguishers	Existing	Status	Recommendation
1.	Water CO ₂ Ext. (09 ltrs.)	02	U/S	02 Nos. required
2.	DCP Extinguisher (6kg)	02	U/S (old model)	02 Nos. required
3.	CO ₂ Extinguisher (4.5kg)	02	U/S	02 Nos. required
4.	Fire Bucket filled with sand and water.	--	--	04 Nos. required

GOVT. SER. SEC.SCHOOL, JOGINDER NAGAR: Type of Building : Single storied semi RCC building

Sl.No	Name of Extinguishers	Existing	Status	Recommendation
1.	Water CO ₂ Ext. (09 ltrs.)	04	U/S (old model)	03 Nos. required
2.	DCP Extinguisher (6kg)	02	U/S (old model)	02 Nos. required
3.	CO ₂ Extinguisher (4.5kg)	02	U/S	02 No. required
4.	Mech. Foam Ext.(09 Ltrs)	04	U/S (old model)	02 Nos. required
4.	Fire Bucket	--	--	04 Nos. To be filled with dry sand.

GOVT. PRIMARY SCHOOL, SHASTRI NAGAR: Type of Building : Single storied semi RCC building:

Sl.No	Name of Extinguishers	Existing	Status	Recommendation
1.	Water CO ₂ Extinguisher (09 Ltrs)	01	U/S (old model)	01 No. required
2.	DCP Extinguisher (6kg)	01	U/S (old model)	01 No. required
3.	CO ₂ Extinguisher (4.5kg)	-Nil-	--	02 Nos. required
4.	Fire Bucket	--	--	04 Nos. To be filled with dry sand.

GOVT. PRIMARY SCHOOL, CHINGAM: Type of Building : Single storied semi RCC building :

Sl.No	Name of Extinguishers	Existing	Status	Recommendation
1.	Water CO ₂ Extinguisher (09 Ltrs)	02	U/S (old model)	02 Nos. required
2.	DCP Extinguisher (6kg)	-Nil-	--	02 Nos. required
3.	CO ₂ Extinguisher (4.5kg)	-Nil-	--	01 No. required
4.	Fire Bucket	-Nil-	--	03 Nos. to be filled with dry sand.

GOVT. PRIMARY SCHOOL, AFRA BAY: Type of Building : Single storied semi RCC building :

Sl.No	Name of Extinguishers	Existing	Status	Recommendation
1.	DCP Extinguisher (6kg)	-Nil-	--	01 No. required
3.	CO ₂ Extinguisher (4.5kg)	-Nil-	--	02 Nos. required
4.	Fire Bucket	-Nil-	--	03 Nos. To be filled with dry sand and water.

GOVT. PRIMARY SCHOOL, CAMPBELL BAY: Type of Building : Single storied semi RCC building:

Sl.No	Name of Extinguishers	Existing	Status	Recommendation
1.	Water CO ₂ Extinguisher (09 Ltrs)	02	U/S (old model)	02 Nos. required
2.	Mech. Foam Ext.(09 Ltrs)	02	U/S (old model)	--
2.	DCP Extinguisher (6kg)	01	U/S (old model)	02 Nos. required
3.	CO ₂ Extinguisher (4.5kg)	02	US	02 Nos. required
4.	Fire Bucket	--	--	03 Nos. filled with dry sand.

Contd.....P3/-

GOVT. MIDDLE SCHOOL, GOVIND NAGAR: Type of Building : **I Block** Double storied semi RCC & **II Block** Single storied semi RCC building-

Sl.No	Name of Extinguishers	Existing	Status	Recommendation
1.	Water CO ₂ Extinguisher (09 Ltrs)	02	U/S (old model)	02 No. required
2.	DCP Extinguisher (6kg)	02	U/S (old model)	01 No. required
3.	CO ₂ Extinguisher (4.5kg)	01	U/S	01 No. required
4.	Fire Bucket	--	--	03 Nos. be filled with dry sand.


GOVT. PRIMARY SCHOOL, LAXMI NAGAR: Type of Building : Single storied semi RCC building -

Sl.No	Name of Extinguishers	Existing	Status	Recommendation
1.	Water CO ₂ Ext. (09 ltrs.)	01	U/S (old model)	01 No. required
2.	DCP Extinguisher (6kg)	01	U/S (old model)	01 No. required
3.	CO ₂ Extinguisher (4.5kg)	-Nil-	--	02 Nos. required
4.	Fire Bucket	-Nil-	--	03 Nos. To be filled with dry sand.

Without training the presence of Fire Extinguishers is vain, thus the training of all teaching and non teaching staffs shall be done from Fire station with prior intimation.

- All extinguishers should be as per IS 15683:2006 with squeeze grip model and should be fixed at 1.5 mtr. above ground level.
- A separate Fire Alarm should be installed for alarming any disaster.
- The cooking facility should be away from the school.
- All school should have sufficient water exclusively for fire fighting.
- A mock drill register to be maintained regarding conduct of evacuation/safety drills at least twice in a year i.e. in the starting session and mid session in which the staff of Fire Station will be the "Observer" of the drill.
- The emergency evacuation plan should be affix in a prominent places to viewed by all incumbent in the school .The plan should also show the location of the fire fighting equipments & emergency contact numbers. The safe Zone may be clearly indicated in the plan.

It is, requested to provide fire extinguishers as per the above recommendation and intimate within a week for re-inspection. The Fire Service on installation of the recommended Fire extinguishers shall provide guidance and training.


(R K SINGH) 06/03/202

Inspector Fire Brigade
Nicobar District, Car Nicobar

Copy to: -

1. R to SP (Fire) for kind information please.
2. ASP (Fire) for kind information please.
3. STO F/S Campbell Bay
4. File concerned.