

CHECKLIST FOR SAFETY AUDIT

Name of the School / HEI: GOUT BOYS' SR. SEC. SCHOOL, PORT BLAIR

	Verify	Yes / No	Remarks
1	Whether the school building is safe for accommodating students?	YES	
2	Whether the Electric Wiring / Electrical appliances are posing threat to occupants?	NO	
3	Whether Potable Water facility is satisfactory?	YES	
4	Whether Portable Fire Fighting Equipments are available?	YES	
5	Are the Chemicals and Equipments of the Laboratory positioned properly considering the safety of children?	YES	
6	Whether there are any high voltage wires / cables / towers in the school premises or its proximity which may prove to be unsafe for occupants?	YES NO	
7	Whether the School Ground safe for students to play?	YES	
8	Whether Disaster Management Plan is available?	YES	
9	Whether the Disaster Management Plan and Committee is updated annually?	NO	Need updation
10	Whether Mock Drills are conducted regularly to acquaint the stakeholders with Disaster preparedness?	YES	
11	Whether First Aid Kit is available?	YES	
12	Whether Medical Emergency Plan is available?	YES	
13	Whether Evacuation Plan is displayed properly?	YES	
14	Whether Emergency Phone Nos. are displayed properly	YES	
15	Whether MDM Kitchen is in hygienic condition?	NA	
16	Whether Staircase and its railing are in good condition?	YES	
17	Whether the classroom walls and ceilings are in good condition?	YES	
18	Whether CCTV cameras are in functional condition?	YES	
19	Open wells / ponds (if exists) in school campus have protective walls and iron grills covering the wells/ponds?	NA	

12/11/2023

Name of the School / H.E.I. _____
 Whether the accommodation is _____
 Whether _____

20	Is the school premises disable friendly?	YES
21	Whether the Water Tank is regularly cleared or not?	YES
22	Whether there is any building in the school campus which is in dilapidated condition and beyond Economical Repair and needs to be removed, considering the safety of occupants.	NO

*The issues, if any, may be indicated in the "Remarks" Column.

23. Recommendations / Suggestions:

sun shades in the secondary Block is in dilapidated cond. need immediate repair, informed concerned APWD site office.

9/18/24

Name & Signature of Committee members

1) _____
 2) _____
 3) _____
 4) _____
 5) _____

[Signature]
 21/08/24
 प्रधान
 Principal

6) _____
 7) _____
 राजकीय बालक वरिष्ठ माध्यमिक विद्यालय
 Govt. Boy's Sr. Sec. School
 मिडिल पॉइन्ट, पोर्ट ब्लेयर / Middle Point, Port Blair

EE, APWD

2

ANNEXURE-I

CHECKLIST FOR SAFETY AUDIT

Name of the School / HEI: *Govt. Boys Sr. Sec. School, Middle point, Port Blair*

	Verify	Yes / No	Remarks
1	Whether the school building is safe for accommodating students?	YES	
2	Whether the Electric Wiring / Electrical appliances are posing threat to occupants?	—	
3	Whether Potable Water facility is satisfactory?	YES	
4	Whether Portable Fire Fighting Equipments are available?	—	
5	Are the Chemicals and Equipments of the Laboratory positioned properly considering the safety of children?	—	
6	Whether there are any high voltage wires / cables / towers in the school premises or its proximity which may prove to be unsafe for occupants?	—	
7	Whether the School Ground safe for students to play?	YES	
8	Whether Disaster Management Plan is available?	—	
9	Whether the Disaster Management Plan and Committee is updated annually?	—	
10	Whether Mock Drills are conducted regularly to acquaint the stakeholders with Disaster preparedness?	—	
11	Whether First Aid Kit is available?	—	
12	Whether Medical Emergency Plan is available?	—	
13	Whether Evacuation Plan is displayed properly?	—	
14	Whether Emergency Phone Nos. are displayed properly	—	
15	Whether MDM Kitchen is in hygienic condition?	—	
16	Whether Staircase and its railing are in good condition?	YES	
17	Whether the classroom walls and ceilings are in good condition?	YES	Renovation work estimate submitted to the division office
18	Whether CCTV cameras are in functional condition?	—	
19	Open wells / ponds (if exists) in school campus have protective walls and iron grills covering the wells/ponds?	—	

22/09/2024

20	Is the school premises disable friendly?	YES	
21	Whether the Water Tank is regularly cleaned or not?	YES	
22	Whether there is any building in the school campus which is in dilapidated condition and beyond Economical Repair and needs to be removed, considering the safety of occupants.	NO	

The issues, if any, may be indicated in the "Remarks" Column.

23 **Recommendations / Suggestions:**

1) Overall ^{major} Repair & Renovation work estimate has been Submitted.

22
09/07/24

Name & Signature of Committee members

1) K. BHANU PRAKASH

2)

3) Junior Engineer
Middle Point Section
SD-1, PND, APWD

5)

6)

7)

[Signature]
21/07/24

Principal
राजकीय बालक वरिष्ठ माध्यमिक विद्यालय
Govt. Boy's. Sr. Sec. School
मिडिल पॉइन्ट, पोर्ट ब्लेयर / Middle Point, Port Blair

Name of the Sch

1	Whether
2	accom