

**Checklist for Safety Audit
GSSS Shaheed Dweep**

| Sl. No. | Verify | Yes/No | Remarks |
|---------|---|--------|--|
| 1. | Whether the School Building is safe for Accommodating Students ? | Yes | Except 02 nos. class rooms for sports and Kishori Club & require floor repair. |
| 2. | Whether the electric wiring / Electrical appliances are posing threat to occupants? | No | -- |
| 3. | Whether Potable Water facility is Satisfactory? | Yes | RO Plant installed. |
| 4. | Whether Portable Fire Fighting Equipments are available? | Yes | Unserviceable. |
| 5. | Are the Chemicals and Equipments of the Laboratory positioned properly considering the safety of children? | Yes | -- |
| 6. | Whether there are any high voltage wires/cables/towers in the school premises or its proximity which may prove to be unsafe for occupants? | No | -- |
| 7. | Whether the School Ground safe for students to play? | Yes | -- |
| 8. | Whether Disaster Management Plan is available? | Yes | -- |
| 9. | Whether the Disaster Management Plan and Committee is updated annually? | Yes | -- |
| 10. | Whether Mock Drills are conducted regularly to acquaint the stakeholders with Disaster Preparedness? | Yes | -- |
| 11. | Whether First Aid Kit is available? | Yes | -- |
| 12. | Whether Medical Emergency Plan is available? | Yes | -- |
| 13. | Whether Evacuation Plan is displayed properly? | Yes | -- |
| 14. | Whether Emergency Phone Nos. are displayed properly? | Yes | -- |
| 15. | Whether MDM Kitchen is in Hygienic condition? | Yes | -- |
| 16. | Whether Staircase and its railing are in good condition? | Yes | -- |
| 17. | Whether the classroom walls and ceiling are in good conditions? | Yes | -- |
| 18. | Whether CCTV cameras are in functional conditions? | Yes | -- |
| 19. | Open wells/ponds (if exists) in School campus have protective walls and iron grills covering the wells/ponds? | Yes | -- |
| 20. | Is the School premises disable friendly? | Yes | -- |
| 21. | Whether the Water Tank is regularly cleaned or not? | Yes | -- |
| 22. | Whether there is any building in the school campus which is in dilapidated condition and beyond Economical Repair and needs to be removed, considering the safety of occupants? | Yes | Two (02) Nos. class rooms for sports and Kishori Clubs. |

* The issues, if any, may be indicated in the "Remarks" column.







Recommendations/Suggestions:

The School Safety Audit was carried out with the objective of ensuring a safe learning environment and potential risks and vulnerabilities with the school premises.

Key Findings:

- Sl. No. 1. Required 02 nos. of room major repair, i.e. roof and floors of sports room and Kishori Club and also required minor repairs of classroom floors, windows and doors.
- Sl. No. 4. Service of all Fire Extinguishers have already been expired.
- Sl. No. 18. Required installation of CCTV Cameras at MDM distribution area and School Play ground inside the Campus.

Name & Signature of Committee Members:

1. 
DR (LTCOH) N. K. BAIDYA
2. 
[JUNIOR ENGINEER(C), CP-I, ARWD, SHDP]
16/08/2024
3. 
[P. K. SAHA, PCCO]
4. 
F/S SHDP
16/8/24
5. 
JE SHDP, Electricity department
(L K SHANKAR GANESH)
- 6.
7. NARAYAN CHANDRA PAUL 
16/8/24
प्रधानाचार्य / Principal
राजकीय वरिष्ठ माध्यमिक विद्यालय / GSSS
शाहीद द्वीप / SHAHEED DWEEP
दक्षिण अण्डमान / SOUTH ANDAMAN