



No.5-193/2023/02/IFB(HQ)/353

निरीक्षक अग्निशमन का कार्यालय

OFFICE OF THE INSPECTOR FIRE BRIGADE
अग्निशमन तथा आपातकालीन सेवा मुख्यालय
FIRE AND EMERGENCY SERVICE HEAD QUARTER

श्री विजयपुरम / Sri Vijaya Puram, दिनांक/dated 13th November, 2024

To,

The Principal
Govt. Sr. Sec. School (RBV)
Sri Vijaya Puram

Sub: - Issuance of Fire Safety Certificate for Govt. RBV School – reg.

Madam/Sir,

With reference to your letter No. 1-4/Building/RBV/2024-25/341 dated 11/11/2024 on the subject cited above, it is to state that fire safety measures have already been recommended vide letter No. No.5-193/2023/02/IFB(HQ)/373 dated 31/10/2023 for compliance.

It is requested that the fire safety recommendations mentioned in the letter dated 31/10/2024 may kindly be complied and submit application through Online Portal "<http://andssw1.and.nic.in/ospfire>".for inspection and consideration of Fire Clearance Certificate.

Yours faithfully

13/11/2024
Inspector Fire Brigade(HQ)
Port Blair

Copy to:-

1. SP(Fire)
2. Dy. SP(Fire)

1.	Foam	01	Unserviceable. To be removed
2.	ABC Power (6 kg)	Nil	01
3.	Co2 (4.5 kg)	Nil	02
4.	Manual Call Point	Nil	01

No.5-193/2023/02/IFB(HQ)/ 373
 निरीक्षक अग्निशमन का कार्यालय
OFFICE OF THE INSPECTOR FIRE BRIGADE
 अग्निशमन मुख्यालय
FIRE SERVICE HEAD QUARTER

पोर्टब्लेयर/PortBlair, दिनांक/dated 31st October,2023

To,
 The Principal
 Govt. Sr. Sec. School (RBV)
 Port Blair

Sub: -Fire Safety audit of Govt. Sr. Sec. School (RBV)- reg.

Sir,

It is to inform you that Fire Safety Audit of Govt. Senior Secondary School RBV, Port Blair was conducted on 26/10/2023 from fire Safety point of view and the following short comings have been noticed.

Sl. No.	Name of fire extinguisher with year of mfg. and equipments	Existing Quantity	Present Recommendation	Status/
BLOCK- 01 (G+1)				
Ground Floor(Class Pre-Primary, Home Science, V A, V C, Store Room)				
1.	ABC Power (6 kg)SP	01	Hydraulic Pressure Testing (HPT) and refilling to be done and certificates to be provided	
2.	DCP (6 kg)CT	01		
3.	Hose Reel	Nil	01	
4.	Fire bucket (with stand)	Nil	04 Nos. to be filled with dry loose sand	
5.	Manual Call Point	Nil	01 No. to be provided	
First Floor (Office, Principal room, Beauty & Wellness room, Class - I B, IIA, Head Master room)				
1.	Water Co2	01	Unserviceable. To be removed	
2.	DCP (5 kg)PT	01		
3.	Co2 (2 kg) (2010)	01	HPT and refilling to be done and certificates to be provided	
4.	Co2 (4.5 kg) (2016)	01		
5.	ABC Power (6 kg)	Nil	01	
6.	Manual Call Point	Nil	01 No. to be provided	
7.	Hose Reel	Nil	01	
BLOCK- 02 Single storey building				
Changing room, Staff room, Music room, Class III A, IV A, I A,				
1.	DCP (5 kg)PT	01	Unserviceable. To be removed	
2.	ABC Power (6 kg)	Nil	01	
3.	Co2 (4.5 kg)	Nil	01	
4.	Manual Call Point	Nil	01 No. to be provided	
5.	Hose Reel	Nil	01	
BLOCK- 03 Single storey building				
Library, Class III B, II B, II C, IV B, V B, Arts & Craft room, II C, Biology LAB				
1.	Foam	01	Unserviceable. To be removed	
2.	ABC Power (6 kg)	Nil	01	
3.	Co2 (4.5 kg)	Nil	02	
4.	Manual Call Point	Nil	01 No. to be provided	